

Farmland Colony No 1 Boundry (1-23)

LEGEND

- ◇ ORIGINAL GOVERNMENT CORNER SEARCHED FOR - NOT FOUND
- ◆ ORIGINAL GOVERNMENT CORNER FOUND
- ◆ FOREST SERVICE CORNER
- ◆ STANDARD B.L.M. CORNER
- ◆ STANDARD D.W.R. CORNER
- ◆ STANDARD BUTTE CORNER - 2" IRON PIPE AND BRASS CAP
- ◓ CORNER MONUMENT - NO HISTORY - SHOWN ON RECORD MAP
- ◒ CORNER MONUMENT - NO HISTORY
- ● ORIGINAL CORNER MONUMENT - SHOWN ON RECORD MAP
- ◐ PROPORTIONED CORNER SET BY SURVEYOR - SHOWN ON RECORD MAP
- ◑ CORNER MONUMENT SET BY SURVEYOR - NOT SHOWN ON RECORD MAP
- ○ CORNER SEARCHED FOR NOT FOUND - DATE OF SEARCH
- □

NOTES

32-PM-25	BOOK 32 OF PARCEL MAPS PAGE 25
32-RS-25	BOOK 32 OF RECORD OF SURVEY MAPS PAGE 25
32- S-25	BOOK 32 OF MAPS (SUBDIVISION) PAGE 25
114-FB-25	BOOK 114 PAGE 25 OF COUNTY SURVEY FIELD NOTES
C-506	MAP ON FILE PUBLIC WORKS DEPARTMENT
CR	CORNER RECORD FILED
PS	PRIVATE SURVEYORS INFORMATION
M.O.R.	MOUND OF ROCKS



Section Corner Index Typical

( ) - Special case

EXAMPLE:

18-3 = South ¼ corner of Section 18

18-F-9 = Center of NW ¼ of SE ¼ of Section 18

Date of last entry _____

COUNTY OF YUBA
DEPARTMENT OF PUBLIC WORKS
MARYSVILLE CALIFORNIA

Section Corner Monumentation
T. 15 N. - R. 3 E. - M.D.B.&M.

DWN. BY	DATE	PROJECT NUMBER
CHK. BY	DATE	
F.B.	SCALE 1"= 2000'	

SHEET 8 OF 29

FILE NO.

PRINTED ON DIEPO NO. 1000H CLEARPRINT